

**Inspection Photos (04/27/2021)**  
**Location Name: UPRR 43 Pan Am G Consolidation No. 2**  
**Remediation No. 16131 - Spill/Release ID 478086**



**Open excavation with a gap in steel panel fencing.**



**Open excavation flooded with groundwater.  
Gap in steel panel fencing.**