

**Inspection Photos (04-27-2021)**  
**Location Name: Paul Heinze No. 1 Flowline**  
**Spill/Release ID 479232**



**Inadequate fencing around open excavation**



**Inadequate Fencing & storm water BMPs**

**Inspection Photos (04-27-2021)**  
**Location Name: Paul Heinze No. 1 Flowline**  
**Spill/Release ID 479232**



**Open excavation flooded with groundwater**



**Oil floating on groundwater in the excavation**

**Inspection Photos (04-27-2021)**  
**Location Name: Paul Heinze No. 1 Flowline**  
**Spill/Release ID 479232**



**Close up of oil floating on groundwater in the excavation**