

Inspection Photos
Location Name: James S Haley Trustee B #2 Flowline
Spill ID 478014 Remediation #16137



COGCC Environmental Inspection
40.07512, -104.97612, 4981.8ft, 106°
04/27/2021 01:55:42 PM



COGCC Environmental Inspection
40.07497, -104.97604, 4991.6ft, 301°
04/27/2021 01:54:46 PM

Photo 1 – Excavation Fencing and stockpiles.

Photo 2 – Impacted soils stockpile; stormwater BMP's not correctly constructed and will channel runoff.

Inspection Photos
Location Name: Peltier #2 Flowline
Spill ID 478542



Photo 3 – Flowline visible in excavation, impacted soils visible.



Photo 4 – Leaking oil from excavation equipment.

Inspection Photos
Location Name: Peltier #2 Flowline
Spill ID 478542



Photo 5 – Mud tracked from location onto public maintained road.



Photo 6 – Location photo