

Inspection Photos
Location Name: Cosslet A 9 Flowline
Spill ID 478542



COGCC Environmental Inspection
40.07555, -104.96654, 4939.1ft, 242°
04/27/2021 01:46:02 PM

Photo 1 – Location photo; impacted soils and trash remain on location.



COGCC Environmental Inspection
40.0754, -104.96675, 4940.7ft, 295°
04/27/2021 01:47:05 PM

Photo 2 – Free product remains in excavation; depth to groundwater has been gradually lowering (naturally).