

Inspection Photos
Operator: Dugan Production
API: 067-06494
Date: 4/22/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the eastern fill slope from the southeastern corner facing northward. Revegetation appears to be progressing with sand dropseed, Indian ricegrass, western wheatgrass, and rubber rabbitbrush.



Photo 3. View of wattles at the top of the eastern cut-slope that need maintenance.



Photo 4. View of reference area comprised of irrigated grass field in a mowed or fallow condition at this time.



Photo 5. View of reference area comprised of pinyon and juniper woodland with sagebrush shrubland, blue grama, Indian ricegrass, and mat penstemon.