

Inspection Photos
UPRR 43 PAN AM G Consolidation #2
Remediation Project #16131/Spill ID 478086 (CL)



Photo 1 – Spill area with open excavation.



Photo 2 – Fencing around open excavation does not adequately protect access to the site.

Inspection Photos
UPRR 43 PAN AM G Consolidation #2
Remediation Project #16131/Spill ID 478086 (CL)



Photo 3 – Fencing around open excavation does not adequately protect access to the site.



Photo 4 – Open excavation. Hydrocarbon sheen observed on groundwater.

Inspection Photos
UPRR 43 PAN AM G Consolidation #2
Remediation Project #16131/Spill ID 478086 (CL)



Photo 5 –Open excavation. Hydrocarbon sheen observed on groundwater.



Photo 6 – Soil stored on location. Lining present under soil stockpile but BMPs are inadequate to prevent stormwater runoff.

Inspection Photos
UPRR 43 PAN AM G Consolidation #2
Remediation Project #16131/Spill ID 478086 (CL)



Photo 7 – BMPs are inadequate around soils stockpile.



Photo 8 – BMPs are inadequate around soils stockpile.

Inspection Photos
UPRR 43 PAN AM G Consolidation #2
Remediation Project #16131/Spill ID 478086 (CL)



Photo 9 – Trash on location.



Photo 10 – Trash on location.