

Inspection Photos
KIEFER GEORGE W UT B #1A
Spill ID 479618 (AC)



Colorado Oil and Gas Conservation Commission
40.04551, -104.85545, 4898.8ft, 125°
04/27/2021 10:18:12 AM

Photo 1 – Spill area. Fencing down around open excavation.



Colorado Oil and Gas Conservation Commission
40.04539, -104.85494, 4895.6ft, 251°
04/27/2021 10:20:20 AM

Photo 2 – Spill area. Area of surface scraping/disturbance extends east of open excavation.

Inspection Photos
KIEFER GEORGE W UT B #1A
Spill ID 479618 (AC)



Photo 3 – Open excavation.



Photo 4 – Open excavation. Impacts appear to remain in situ below flowline repair.

Inspection Photos
KIEFER GEORGE W UT B #1A
Spill ID 479618 (AC)



Photo 5 – Soil stored on location with inadequate BMPs.



Photo 6 – Soil stored on location with inadequate BMPs.

Inspection Photos
KIEFER GEORGE W UT B #1A
Spill ID 479618 (AC)



Photo 7 – Soil stored on location with inadequate BMPs.



Photo 8 – Additional disturbed area north of open excavation