

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/27/2021

Submitted Date:

04/29/2021

Document Number:

689501209

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: Brown, Kari On-Site Inspection 2A Doc Num: _____

Operator Information:
OGCC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1675 BROADWAY, STE 2800
City: DENVER State: CO Zip: 80202

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:
4 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, KPK		cogcc@kpk.com	All Inspections
,		mknop@kpk.com	
Axelson, John		john.axelson@state.co.us	
Canfield, Chris		chris.canfield@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
469095	SPILL OR RELEASE	CL	08/04/2020		-	Facility #8 Consolidation Line	EI

General Comment:
This is a follow-up inspection to Doc # 689501184; environmental inspection of Remediation Project No. 15773/Spill ID 469095 (CL). No changes have occurred at the site since the previous inspection. Any corrective actions from previous inspections that have not been addressed are still applicable.

There were no operator or contract environmental personnel on location at the time of this field inspection.

Photos attached to document site conditions.

Inspected Facilities

Facility ID: 469095 Type: SPILL OR API Number: - Status: CL Insp. Status: EI

Environmental

Spills/Releases:

Type of Spill: _____ Estimated Spill Volume: _____

Comment: Excavation documented in Inspection Doc #690101562 (12/5/2019) opened to repair flowlines has been backfilled. No equipment or personnel were on site at the time of inspection, and no work appears to have been conducted on site since initial actions taken to repair flowlines. Form 27 Doc # 402646205 (4/1/2021) reports excavation is ongoing to chase out the extents of the impacts'

Corrective Action: Operaor shall submit a Supplemental Form 27 with and updated and accurate implementation schedule. Date: 04/26/2021

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

Waste Management:

Type	Management	Condition	GPS (Lat)	(Long)	
Comment		No impacted material stored on site.			
Corrective Action					Date: _____

Spill/Remediation:

Comment: _____
 Corrective Action: _____ Date: _____

Emission Control Burner (ECB): _____
 Comment: _____
 Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689501210	Remediation Area	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5416940