

Inspection Photos  
Operator: Simcoe  
API: 067-08496  
Date: 4/22/2021



Photo 1. View of the project area from the well pad entrance facing center.





Photo 2. View of the southern fill slope from the southeastern corner facing westward. Revegetation is progressing in portions of the fill slope, largely with sand dropseed. Other portions remain sparse and weedy, and will require re-seeding if cover is not increasing during the growing season.





Photo 3. View of the eastern project area from the northeastern corner facing southward.





Photo 4. View of dense musk thistle rosettes within the eastern project area. Approximately 250 individuals observed.





Photo 5. View of the reference area comprised of pinyon and juniper woodland with sagebrush shrubland, blue grama, Indian ricegrass, and mat penstemon.