

## Inspection Photos

Location Name: SG INTERESTS I LTD HENDERSON-611S90W /9SWNE

Location ID: 324477



Photo #3671 from entrance to location.



Photo #3672 location lacks stabilization.



## Inspection Photos

Location Name: SG INTERESTS I LTD HENDERSON-611S90W /9SWNE

Location ID: 324477



**Photo #3673 location lacks stabilization.**



**Photo #3674 No form of tracking BMP at entrance to location.**



## Inspection Photos

Location Name: SG INTERESTS I LTD HENDERSON-611S90W /9SWNE

Location ID: 324477



**Photo #3675 Culvert capacity reduced due to inlet being crushed.**

