

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/28/2021

Submitted Date:

04/29/2021

Document Number:

699803008

FIELD INSPECTION FORMLoc ID 324218 Inspector Name: De Paolo, Corey On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: PO BOX 370

City: PARACHUTE State: CO Zip: 81635

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

17 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
, TEP		COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
265427	WELL	PR	12/09/2002	GW	045-09012	PUCKETT/TOSCO PA 24-34	PR
265428	WELL	PR	04/07/2003	OW	045-09013	PUCKETT/TOSCO PA 324-34	PR

General Comment:**COGCC Inspection Report Summary**

On Wednesday 4/28/21 at approximately 15:00 hours, I, Inspector Corey De Paolo, Conducted an on-site inspection at TEP ROCKY MOUNTAIN LLC PUCKETT/TOSCO-66S95W /34SESW, Location #324218 in Garfield County Colorado.

While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1) Rill erosion occurring in multiple places on location. No velocity checks. Sediment is being transported off of location with a corrective action date of 5/13/21.

- Location is located on in a high priority habitat area.

A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

LocationOverall Good: ☒

Signs/Marker:			
Type	CONTAINERS		
Comment:	Chemical tank		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Battery sign missing required information		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Ancillary equipment	# 1		
Comment:	Chemical tank by wellheads		
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		

Comment:	All meter runs have been calibrated in the last year.		Date:	
Corrective Action:			Date:	
Type: Bird Protectors	# 2			
Comment:			Date:	
Corrective Action:			Date:	
Type: Plunger Lift	# 2			
Comment:	All wells on plunger lift		Date:	
Corrective Action:			Date:	
Type: Horizontal Heated Separator	# 2			
Comment:			Date:	
Corrective Action:			Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected FacilitiesFacility ID: 265427 Type: WELL API Number: 045-09012 Status: PR Insp. Status: PR**Producing Well**Comment: Producing

Corrective Action:

Date:

Facility ID: 265428 Type: WELL API Number: 045-09013 Status: PR Insp. Status: PR**Producing Well**Comment: Producing

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts				
		Gravel				
Check Dams	Fail					No velocity checks
Ditches	Fail					Rill erosion occurring
Berms						
Sediment Traps						
		Berms				
		Ditches				
Gravel						Gravel by wellheads
		Compaction				
Compaction						

Comment: Rill erosion occurring in multiple places on location. No velocity checks. Sediment is being transported off of location.

Corrective Action: oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations.

Date: 05/13/2021

Pits: ☒ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Refer to Storm water for corrective actions. Location is a triple lease with a centralized tank battery.	depaoloc	04/28/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699803017	Photos for Insp. #699803008	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5417057