

**Inspection Photos**  
**Location Name: John Weigandt Consolidation**  
**Spill ID 465402**



**Photo 1 – Livestock adjacent to excavation with inadequate fencing to control cattle.**



**Photo 2 – Excavation photo**

**Inspection Photos**  
**Location Name: John Weigandt Consolidation**  
**Spill ID 465402**



**Photo 3 – Inadequate fencing with gaps**

**Photo 4 – Inadequate fencing with gaps**

**Inspection Photos**  
**Location Name: John Weigandt Consolidation**  
**Spill ID 465402**



COGCC Environmental Inspection  
40.00197, -104.87651, 5014.2ft, 151°  
04/27/2021 10:58:20 AM

**Photo 5 –Flow line visible in excavation**



COGCC Environmental Inspection  
40.00201, -104.87647, 5010.0ft, 197°  
04/27/2021 10:58:07 AM

**Photo 6 – Flow line visible in excavation**

**Inspection Photos**  
**Location Name: John Weigandt Consolidation**  
**Spill ID 465402**



**Photo 7 – Flowline and stained soil in excavation**



**Photo 8 – Location photo**

**Inspection Photos**  
**Location Name: John Weigandt Consolidation**  
**Spill ID 465402**



**Photo 9 – Stained soils remain on surface adjacent to excavation.**



**Photo 10 – Stained soils remain on surface adjacent to excavation.**