

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/26/2021

Submitted Date:

04/26/2021

Document Number:

699303761

**FIELD INSPECTION FORM**

Loc ID 332957 Inspector Name: Revas, Robbie On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 46290  
Name of Operator: KP KAUFFMAN COMPANY INC  
Address: 1675 BROADWAY, STE 2800  
City: DENVER State: CO Zip: 80202

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 13 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		cogcc@kpk.com	<a href="#">All Inspections</a>
,		rwatzman@kpk.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241146	WELL	PR	12/01/2020	OW	123-08934	MARGARET TWOMBLY 'B' 3	SI

**General Comment:**

*(This area is currently blank for general comments.)*

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Sign not legible		
Corrective Action:	Comply with Rule 605 g	Date:	07/26/2021

Emergency Contact Number:		
Comment:	<input type="text"/>	
Corrective Action:	<input type="text"/>	Date: _____

<b>Good Housekeeping:</b>			
Type	WEEDS		
Comment:	Dead weeds all around location		
Corrective Action:	Comply with Rule 606	Date:	07/26/2021

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	PUMP JACK		
Comment:	hog fence		
Corrective Action:		Date:	
Type	OTHER		
Comment:	ancillary equipment has fabricated steel pipe and round stock		
Corrective Action:		Date:	
Type	OTHER		
Comment:	electric box, antenna has fabricated steel pipe and round stock		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Ancillary equipment	# 1		
Comment:	meter box, electric panel and transformers		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	phone line and antenna?		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	appear to be plumbed to surface		
Corrective Action:		Date:	

Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	electric motor		
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 241146 Type: WELL API Number: 123-08934 Status: PR Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Scout card show well as PR at the time of inspection well is SI, valves are closed electric panel is shut off and there is no meter on the meter box.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 11/01/2020 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary                      On Monday 4/26/2021 at approximately 1515 hrs. I, Inspector Robbie Revas,                      Conducted an on-site inspection at a KP Kauffman location:</p> <p style="text-align: right;">Margaret Twombly B #3 at API #05-123-08934 in Weld County Colorado.</p> <p>While there, I observed a wellsite, SI at the time of inspection.                      During this inspection the following possible compliance issues were observed:                      605.g Signs: WH sign is faded and has fallen to the ground, CA date 7-26-2021.                      606 Housekeeping: Dead weeds all around well site, CA date 7-26-2021.                      There is a wooden pole with an antenna on it that has fallen over and is leaning on its                      fencing that needs to be addressed.                      See attached photos.                      Location: dry, Weather: cloudy.                      A follow up on this site inspection needs to be conducted to ensure the                      Compliance issues have been corrected to comply with COGCC rules.                      This is a summary of inspection report.</p>	revasr	04/26/2021

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402671421	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5413334">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5413334</a>
699303762	location pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5413330">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5413330</a>