

Inspection Photos

API: 071-07560

Operator: TIMBER CREEK OPERATING

Inspection Date: 4/30/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07560 | Date: 4/30/2021

Inspection Photos



Photo 1. There is vehicle rutting along the road traveling to the location. The road needs to be maintained. Previous corrective action has not been completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07560 | Date: 4/30/2021

Inspection Photos



Photo 2. Facing southeast along the access road. There is a low spot in the road where stormwater accumulates. This area needs to be repaired to allow proper drainage. E.g. load of roadbase to repair and stabilize this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07560 | Date: 4/30/2021

Inspection Photos



Photo 3. Likewise to previous photo. There is a low spot in the road where stormwater accumulates and vehicles are widening the road to avoid this area. This area needs to be repaired to allow proper drainage.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07560 | Date: 4/30/2021

Inspection Photos



Photo 4. There is vehicle rutting along the road traveling to the location. The road needs to be maintained.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07560 | Date: 4/30/2021

Inspection Photos



Photo 5. Facing east toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07560 | Date: 4/30/2021

Inspection Photos



Photo 6. Facing toward the location. Areas of rutting at the location need to be repaired and stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07560 | Date: 4/30/2021

Inspection Photos



Photo 7. Stained soils near engine have been cleaned up.

