

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/13/2021

Submitted Date:

04/25/2021

Document Number:

688310376

FIELD INSPECTION FORM

Loc ID 435414 Inspector Name: Sherman, Susan On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10706
Name of Operator: D90 ENERGY LLC
Address: 202 TRAVIS STREET #402
City: HOUSTON State: TX Zip: 77002

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 7 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Craig, Bill	719-650-4991	jwcranch@gmail.com	
Oakes, Kevin	713-227-0391	kevin@d90energy.com	Designated Agent
James, Cole	719-892-0378	cj0378@hotmail.com	Pumper

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
435415	WELL	SI	06/01/2018	OW	073-06568	JOHN CRAIG 4-2	TA

General Comment:

Reinspection, MIT-document #402645869 21 -00 Test Date: 12/10/2019 Final Case Pressure: 360 Pressure Loss or Gain: -2 Bridge Plug Depth: /Top Packer Depth: 7044 IN PROCESS

See document #402492194 WARN -00 Letter IN PROCESS for Form 7s requirement, 10/2020 last reported production to database

Document #402190896 10 (CO)(CC) Type: Change of Operator IN PROCESS 3/25/2020

Location

Overall Good:

Signs/Marker:

Type WELLHEAD

Comment: D90 signs-Form 10 is in process

Corrective Action:

Date:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type WELLHEAD

Comment:

Corrective Action:

Date:

Type LOCATION

Comment:

Corrective Action:

Date:

Equipment:

corrective date

Type: Bradenhead

1

Comment:

Corrective Action:

Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		

Comment:

Corrective Action:

Date:

Paint

Condition

Other (Content)

Other (Capacity)

Other (Type)

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment:		
Corrective Action:		Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

--	--

Inspected Facilities

Facility ID: 435415 Type: WELL API Number: 073-06568 Status: SI Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Form 7s to 10/2020, not up to date, See document #402492194 WARN -00 Letter IN PROCESS

Corrective Action: Operator shall submit any delinquent forms, notices, or reports; and correct any incomplete or inaccurate reports. Confirm that all required Form 7s are submitted, accurate, and up-to-date.

Date: 01/15/2021

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Other	Pass					other-vegetation
Compaction	Pass	Compaction	Pass			

Comment: [fenced in pasture](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402671646	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5413548
688310414	D90 Energy John Craig 4-2	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5413539