

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/04/2021

Submitted Date:

05/04/2021

Document Number:

696303211

FIELD INSPECTION FORM

Loc ID 470277 Inspector Name: PETRIE, ERICA On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1675 BROADWAY, STE 2800
City: DENVER State: CO Zip: 80202

Findings:

- 11 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		cogcc@kpk.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
470277	Location	AC			-	Seyfried 63N62W1SESW	AC

General Comment:

[Production Facility Inspection - Follow-Up Inspection to FIR 696302292 dated 08.20.2020](#)

Location			
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Produced Water Tank - Content and Capacity are missing; see photos		
Corrective Action:	Install sign to comply with Rule 605.h.		Date: <u>06/04/2021</u>
Type	BATTERY		
Comment:	Adequate		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:	<input style="width: 100%;" type="text"/>		Date: _____
Good Housekeeping:			
Type	STORAGE OF SUPL		
Comment:	Unused Heater Treater west of Tank Berm, STILL REMAINS. Same Corrective Action Date remains. See photos		
Corrective Action:	Comply with Rule 606		Date: <u>11/20/2020</u>
Type	UNUSED EQUIPMENT		
Comment:	Unmarked Risers at Separator; see photos		
Corrective Action:	Comply with Rule 606		Date: <u>05/19/2021</u>
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:	<input style="width: 100%;" type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	TANK BATTERY		
Comment:	Barbed Wire		
Corrective Action:			Date:
Type	SEPARATOR		
Comment:	Barbed Wire		
Corrective Action:			Date:
Equipment:			
Type: Gas Meter Run			# 1
Comment:			No current Calibration Card, please contact Gas Operating Company to provide current Calibration card
Corrective Action:			Calibrate gas metering equipment annually to comply with rule 430.d.(1).
			Date: <u>08/06/2021</u>
Type: Horizontal Heated Separator			# 1
Comment:			

Corrective Action:	Date:
--------------------	-------

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	FIBERGLASS AST		

Comment:	
Corrective Action:	Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment: Shares berm with the Crude Oil Tank				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		40.249340,-104.274610

Comment:	
Corrective Action:	Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO			
Comment:				
Corrective Action:				Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 470277 Type: Location API Number: - Status: AC Insp. Status: AC

Producing Well

Comment: [Location Shut-In at the time of this Inspection.](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit						
Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				
Comment: <input style="width:90%;" type="text"/> Corrective Action: <input style="width:90%;" type="text"/>						Date: _____
Pits: <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT						

COGCC Comments		
Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Thursday 04/29/2021 at approximately 14:42, I, Inspector Erica Petrie, conducted a Follow-Up Field Inspection at KP Kauffman Company, Seyfried #2 Tank Battery, Location #470277 in Weld County, Colorado.</p> <p>While there, I observed Production Operations</p> <p>During this Inspection the following possible compliance issues were observed:</p> <p>Produced Water Tank - Content and Capacity Labels are Fading. See photos. Comply with Rule 605.h. Corrective Action Date 06.04.2021</p> <p>Weeds are actively growing on Location. See photos. Comply with Rule 606. Corrective Action Date 05.19.2021</p> <p>Unmarked Risers at Separator. See photos. Comply with Rule 606. Corrective Action Date 05.19.2021</p> <p>Unused Heater Treater on the West side of Tanks STILL REMAINS; the same Corrective Action date remains, see photos. Comply with Rule 606. Corrective Action date 11.20.2020</p> <p>Calibration Card in Meter House NOT Current, please contact Gas Operating Company for current Calibration Card. See photos. Calibrate gas metering equipment annually to comply with rule 430.d.(1). Corrective Action Date 08.06.2021</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of the Inspection Report.</p>	petrie	05/04/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696303212	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5420546