

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/26/2021

Submitted Date:

04/27/2021

Document Number:

699802988

FIELD INSPECTION FORM

 Loc ID: 334466
 Inspector Name: De Paolo, Corey
 On-Site Inspection:
 2A Doc Num:
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 24 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Operator Information:
 OGCC Operator Number: 10433
 Name of Operator: LARAMIE ENERGY LLC
 Address: 1401 17TH STREET SUITE #1400
 City: DENVER State: CO Zip: 80202
Contact Information:

| Contact Name | Phone | Email | Comment |
|-----------------|-------|---------------------------------------|---------|
| Kellerby, Shaun | | shaun.kellerby@state.co.us | |
| , Laramie | | cogccnotifications@laramie-energy.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 294176 | WELL | PR | 03/12/2008 | GW | 077-09468 | NVEGA 23-434 | PR |
| 294715 | WELL | PR | 02/27/2008 | GW | 077-09503 | NVEGA 23-441 | PR |
| 294716 | WELL | PR | 02/27/2008 | GW | 077-09504 | NVEGA 23-431 | PR |
| 294717 | WELL | PR | 11/01/2018 | GW | 077-09505 | NVEGA 23-424 | PR |
| 294718 | WELL | PR | 02/27/2008 | GW | 077-09506 | NVEGA 24-134 | PR |
| 294719 | WELL | PR | 02/27/2008 | GW | 077-09507 | NVEGA 24-141 | PR |
| 294720 | WELL | PR | 02/27/2008 | GW | 077-09508 | NVEGA 24-131 | PR |
| 294721 | WELL | PR | 02/27/2008 | GW | 077-09509 | NVEGA 24-144 | PR |
| 294722 | WELL | PR | 02/27/2008 | GW | 077-09510 | NVEGA 23-444 | PR |

General Comment:**COGCC Inspection Report Summary**

On Monday 4/26/21 at approximately 14:00 hours, I, Inspector Corey De Paolo, Conducted an on-site inspection at LARAMIE ENERGY LLC NVega /5B Pad, Location #334466 in Mesa County Colorado.

While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

- 1) No battery sign located at the tank battery with a corrective action date of 7/26/21.
- 2) Location lacks stabilization. No form of tracking BMP at entrance to location with a corrective action date of 5/11/21.

- Location is located on in a high priority habitat area.

A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location

Overall Good:

Signs/Marker:

| | | | |
|--------------------|--|-------|------------|
| Type | BATTERY | | |
| Comment: | No battery sign located at the tank battery. | | |
| Corrective Action: | A permanent, conspicuous sign will be located at the tank battery. | Date: | 07/26/2021 |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

| | | | |
|--------------------|-----|-------|--|
| Comment: | 911 | Date: | |
| Corrective Action: | | Date: | |

Overall Good:

Spills:

| Type | Area | Volume | | |
|------|------|--------|--|--|
| | | | | |

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

| | | | |
|--------------------|------------------|-------|--|
| Type | WELLHEAD | | |
| Comment: | Livestock panels | | |
| Corrective Action: | | Date: | |

Equipment:

| Type | | | corrective date |
|-----------------------------------|--|-------|-----------------|
| Type: Gas Meter Run | # 1 | | |
| Comment: | Separate from separators | | |
| Corrective Action: | | Date: | |
| Type: Horizontal Heated Separator | # 9 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Plunger Lift | # 9 | | |
| Comment: | All wells on plunger lift | | |
| Corrective Action: | | Date: | |
| Type: Bradenhead | # 9 | | |
| Comment: | No form of pressure monitoring equipment located on braden heads. All braden head valves are accessible. | | |
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 9 | | |

| | | | | |
|-----------------------|---|--|-------|--|
| Comment: | All meter runs have been calibrated in the last year. | | Date: | |
| Corrective Action: | | | Date: | |
| Type: Pig Station | # 5 | | | |
| Comment: | | | Date: | |
| Corrective Action: | | | Date: | |
| Type: Bird Protectors | # 3 | | | |
| Comment: | | | Date: | |
| Corrective Action: | | | Date: | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| METHANOL | 1 | <50 BBLs | STEEL AST | | , |
| Comment: | | | | | Date: |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|------------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | 500 gallon | |
| Other (Type) | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------------------|---------------------|---------------------|-------------|
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | Separate containment | | | Date: |
| Corrective Action: | | | | Date: |

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| CONDENSATE | 4 | 400 BBLs | STEEL AST | | , |
| Comment: | | | | | Date: |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | | | | Date: |
| Corrective Action: | | | | Date: |

Venting:

| | | |
|--------|----|--|
| Yes/No | NO | |
|--------|----|--|

| | | | |
|--------------------|--|-------|--|
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | | |
|--------------------|--|-------|--|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| Inspected Facilities | | | | | | | | | |
|-----------------------|-----------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 294176 | Type: | WELL | API Number: | 077-09468 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing | | | | Date: | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | 294715 | Type: | WELL | API Number: | 077-09503 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing | | | | Date: | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | 294716 | Type: | WELL | API Number: | 077-09504 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing | | | | Date: | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | 294717 | Type: | WELL | API Number: | 077-09505 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing | | | | Date: | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | 294718 | Type: | WELL | API Number: | 077-09506 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing | | | | Date: | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | 294719 | Type: | WELL | API Number: | 077-09507 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing | | | | Date: | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | 294720 | Type: | WELL | API Number: | 077-09508 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing | | | | Date: | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | 294721 | Type: | WELL | API Number: | 077-09509 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing | | | | Date: | | | | |
| Corrective Action: | | | | | Date: | | | | |

Facility ID: 294722 Type: WELL API Number: 077-09510 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|--|--------------------------|---|
| Gravel | Fail | | | | | Gravel insufficient |
| Berms | | | | | | |
| | | Gravel | | | | |
| Other | Fail | | | | | No form of tracking BMP at entrance to location |
| Ditches | | | | | | |
| Check Dams | | | | | | |
| Compaction | Fail | | | | | Location lacks stabilization. |
| | | Berms | | | | |
| | | Ditches | | | | |
| | | Rip Rap | | | | |
| | | Check Dams | | | | |
| | | | | Material Handling And Spill Prevention | | Methonal tank |
| | | Culverts | | | | |
| | | Sediment Traps | | | | |
| Sediment Traps | | | | | | |

Comment: Location lacks stabilization. No form of tracking BMP at entrance to location.

Corrective Action: Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations.

Date: 05/11/2021

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

| Comment | User | Date |
|--|----------|------------|
| Refer to Signs/Markers and Storm water for corrective actions. | depaoloc | 04/27/2021 |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-----------------------------|---|
| 402673359 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5414976 |
| 699802989 | Photos for Insp. #699802988 | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5414965 |