

Inspection Photos

Location Name: CAERUS PICEANCE LLC ORCHARD-68S96W /10NWSE

Location ID: 312690



Photo #3690 from entrance to location.



Photo #3696 No tank battery sign located at tank battery.

Inspection Photos

Location Name: CAERUS PICEANCE LLC ORCHARD-68S96W /10NWSE

Location ID: 312690



Photo #3691 Location lacks stabilization.



Photo #3296 from inspection #699802829 conducted on 3/26/21.

Inspection Photos

Location Name: CAERUS PICEANCE LLC ORCHARD-68S96W /10NWSE

Location ID: 312690



Photo #3694 Gully erosion occurring on Eastside of access road.



Photo #3303 from inspection #699802829 conducted on 3/26/21.

Inspection Photos

Location Name: CAERUS PICEANCE LLC ORCHARD-68S96W /10NWSE

Location ID: 312690



Photo #3695 Run on to location is not being controlled.



Photo #3693 Sediment is encroaching on tank containment.

Inspection Photos

Location Name: CAERUS PICEANCE LLC ORCHARD-68S96W /10NWSE

Location ID: 312690



Photo #3300 from inspection #699802829 conducted on 3/26/21.



Photo #3697 Heating insulation open ended and not capped.

Inspection Photos

Location Name: CAERUS PICEANCE LLC ORCHARD-68S96W /10NWSE

Location ID: 312690



Network time is not synchronized
Local: May 4, 2021 at 1:39:07 PM MDT



Network time is not synchronized
Local: Mar 26, 2021 at 2:40:08 PM MDT

Photo #3698 no form of tracking control at entrance to location.

Photo #3297 from inspection #699802829 conducted on 3/26/21.