

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

05/05/2021

Submitted Date:

05/05/2021

Document Number:

679603864

FIELD INSPECTION FORM
 Loc ID 418007 Inspector Name: Santistevan, Brittani On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 10611

Name of Operator: LONGS PEAK RESOURCES LLC

Address: 2727 ALLEN PARKWAY SUITE 1850

City: HOUSTON State: TX Zip: 77019

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

7 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Galvan, Angie		angie.galvan@boomtownoil.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
418006	WELL	SI	06/01/2018	OW	123-31810	LAZY D ZN 03-15HZ	TA

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Two tanks have signage that is no longer legible. See attached photo.		
Corrective Action:	Install sign to comply with Rule 605h.	Date:	08/05/2021
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: No 24hr operator emergency # displayed. See attached photo.

Corrective Action: Install sign to comply with Rule 605.e.

Date: 08/05/2021

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Unused equipment, unused risers on various parts of location. See attached photos		
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume	
------	------	--------	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type		
Comment:		
Corrective Action:		Date:

Equipment:

Type: Pump Jack	# 1		corrective date
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER	1	OTHER	PBV FIBERGLASS		,
Comment:					
Corrective Action:		Date:			

Paint

Condition	Adequate
Other (Content)	UNKNOWN
Other (Capacity)	UNKNOWN

Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment: Shares containment with other tanks.						
Corrective Action:						Date:
Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	400 BBLS	STEEL AST		,	
Comment:						
Corrective Action:						Date:
<u>Paint</u>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate		
Comment:						
Corrective Action:						Date:
Contents	#	Capacity	Type	Tank ID	SE GPS	
OTHER	1	OTHER	STEEL AST		,	
Comment:						
Corrective Action:						Date:
<u>Paint</u>						
Condition	Adequate					
Other (Content) UNKNOWN						
Other (Capacity) UNKNOWN						
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment: Shares containment with other tanks.						
Corrective Action:						Date:
<u>Venting:</u>						
Yes/No	NO					
Comment:						
Corrective Action:						Date:
<u>Flaring:</u>						
Type						

Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 418006 Type: WELL API Number: 123-31810 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily AbandonedReminder: EQUIPMENT PRESENT/DISCONNECTEDComment: TAForm 4 DOC#: 402495403 (in process)Corrective Action: Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>**Weather Conditions: raining, mud</p> <p>On Tuesday, May 4, 2021 at approximately 14:45, I, Inspector Brittani Santistevan, conducted an on-site inspection at LAZY D ZN 03-15HZ (Longs Peak Resources), at location #: 458561 in WELD COUNTY Colorado.</p> <p>While there, I observed a shut in facility.</p> <p>During this inspection the following possible compliance issues were observed:</p> <ol style="list-style-type: none"> 1. No 24hr operator emergency # displayed on tank battery sign/wellhead sign. Install sign to comply with Rule 605.e. (Corrective Action Date: August 5, 2021) See attached photo #1. 2. Two tanks display signs that are no longer legible. Install sign to comply with Rule 605h. (Corrective Action Date: August 5, 2021) See attached photos #2, 3. 3. Unused equipment near tank battery and wellhead. Unused risers south of tank battery. Risers must be LO/TO within 24 HRS by operator or remove. (Corrective Active Date: August 5, 2021) See attached photos #5, 6. <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	santistb	05/05/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679603865	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5420870