

**Inspection Photos**  
**UPRR 43 PAN AM G Consolidation #2**  
**Remediation Project #16131/Spill ID 478086 (CL)**



**Photo 1 – Spill area with open excavation.**



**Photo 2 – Fencing around open excavation does not adequately protect access to the site.**



**Inspection Photos**  
**UPRR 43 PAN AM G Consolidation #2**  
**Remediation Project #16131/Spill ID 478086 (CL)**



**Photo 3 – Fencing around open excavation does not adequately protect access to the site.**



**Photo 4 – Open excavation. Impacts appear to remain in situ. Hydrocarbon sheen observed on groundwater.**



**Inspection Photos**  
**UPRR 43 PAN AM G Consolidation #2**  
**Remediation Project #16131/Spill ID 478086 (CL)**



**Photo 5 –Open excavation. Hydrocarbon sheen observed on groundwater.**



**Photo 6 – Soil stored on location. Lining present under soil stockpile but BMPs are inadequate to prevent stormwater runoff.**



**Inspection Photos**  
**UPRR 43 PAN AM G Consolidation #2**  
**Remediation Project #16131/Spill ID 478086 (CL)**



**Photo 7 – Trash on location.**



**Photo 8 – Trash on location.**