

Inspection Photos
KIEFER GEORGE W UT B #1A
Spill ID 479618 (AC)



Photo 1 – Spill area. Fencing repaired around open excavation.



Photo 2 – Spill area. Area of surface scraping/disturbance extends east of open excavation.

Inspection Photos
KIEFER GEORGE W UT B #1A
Spill ID 479618 (AC)



Photo 3 – Open excavation.



Photo 4 – Soil stored on location with inadequate BMPs.