

Inspection Photos

API: 009-06081

Operator: DOVER ATWOOD CORPORATION

Inspection Date: 5/5/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 009-06081 | Date: 5/5/2021

Inspection Photos



Photo 1. Facing east toward the location..



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06081 | Date: 5/5/2021

Inspection Photos



Photo 2. The tank is marked as not in use and labeled Produced Water. Next photo shows oily fluids inside the tank which apparently the tank is in use. Secondary containment is inadequate to contain 150% of the volume of the tank.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06081 | Date: 5/5/2021

Inspection Photos




Photo 3. View of oil fluids inside the tank. Tank is labeled Produced Water which is not accurately labeled.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06081 | Date: 5/5/2021

Inspection Photos



Photo 4. The unused pipe has been removed. There is a pipe riser shown at red arrow with no LOTO.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06081 | Date: 5/5/2021

Inspection Photos



Photo 5. The well sign does not comply with 605. The gate and fence around the pumpjack has been repaired.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06081 | Date: 5/5/2021

Inspection Photos



Photo 6. The well sign does not comply with 605. Incorrect Operator name and missing information.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06081 | Date: 5/5/2021