

# Inspection Photos

API: 009-06047

Operator: DOVER ATWOOD CORPORATION

Inspection Date: 5/5/2021



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06047 | Date: 5/5/2021

## Inspection Photos



**Photo 1.** Facing east toward the location..



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06047 | Date: 5/5/2021

## Inspection Photos



**Photo 2.** The well sign does not comply with 605. Incorrect Operator name and missing information. Missing tank NFPA labeling and missing INFO.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06047 | Date: 5/5/2021

## Inspection Photos



**Photo 3.** The fencing around the pump jack is not maintained and is laying on the ground.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06047 | Date: 5/5/2021

## Inspection Photos



**Photo 4.** The tank is marked as not in use and labeled Produced Water. Next photo shows fluids inside the tank which apparently the tank is in use. Secondary containment is inadequate to contain 150% of the volume of the tank.




**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06047 | Date: 5/5/2021

## Inspection Photos



**Photo 5.** View of fluids inside the tank. Tank is labeled Produced Water



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06047 | Date: 5/5/2021