

Inspection Photos
Operator: Williford Res.
API: 067-05446
Date: 5/5/2021



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the western project area facing northward from the southwestern corner. Revegetation is progressing, largely with crested wheatgrass.



Photo 3. View of the southern project area from the southwestern corner facing eastward.



Photo 4. View of wood debris near the wellhead,needs to be removed and properly disposed of.



Photo 5. View of weed debris within the tank battery area west of the well.



Photo 6. View of reference area comprised of sagebrush shrubland with grasses such as squirreltail and James galleta. Scattered pinyon and juniper trees are present.