

Inspection Photos  
Operator: Williford Res.  
API: 067-05758  
Date: 5/5/2021



Photo 1. View of the project area from the northwestern corner facing center. Area is graded, young grasses crested wheatgrass observed.





Photo 2. View of the western project area facing southward from the northwestern corner.





Photo 3. View of Russian knapweeds within the northern project area.





Photo 3. View of risers that remain within the northeastern project area, need to be properly abandoned and removed.





Photo 4. View of reference area comprised of mixed sagebrush and grass field with crested wheatgrass.