

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/26/2021

Submitted Date:

05/07/2021

Document Number:

689805705**FIELD INSPECTION FORM**Loc ID 313138 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10133Name of Operator: HILCORP ENERGY COMPANYAddress: P O BOX 61229City: HOUSTON State: TX Zip: 77208**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**5 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name  | Phone          | Email                | Comment                         |
|---------------|----------------|----------------------|---------------------------------|
| Fillpot, Greg | (307) 299-3829 | gfillpot@hilcorp.com | <a href="#">All Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 260476      | WELL | PR     | 06/21/2001  | GW         | 081-07062 | VAN SCHAICK 6 | SI          |

**General Comment:**Routine FIU inspection. Compliance issues observed:  
[no bradenhead access apparent](#)

**Location**Overall Good: ☒**Signs/Marker:**

|                    |                      |       |  |
|--------------------|----------------------|-------|--|
| Type               | TANK LABELS/PLACARDS |       |  |
| Comment:           |                      |       |  |
| Corrective Action: |                      | Date: |  |
| Type               | WELLHEAD             |       |  |
| Comment:           |                      |       |  |
| Corrective Action: |                      | Date: |  |
| Type               | BATTERY              |       |  |
| Comment:           |                      |       |  |
| Corrective Action: |                      | Date: |  |

Emergency Contact Number:

Comment: 713-209-2400

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒**Spills:**

|      |      |        |  |  |
|------|------|--------|--|--|
| Type | Area | Volume |  |  |
|------|------|--------|--|--|

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

|                                 |   |       |                 |
|---------------------------------|---|-------|-----------------|
| Type: Bradenhead                | #   |       | corrective date |
| Comment:                        | No bradenhead access apparent.  |       |                 |
| Corrective Action:              | Install bradenhead access and/or means of monitoring bradenhead pressure. | Date: | 06/07/2021      |
| Type: Plunger Lift              | # 1   |       |                 |
| Comment:                        |   |       |                 |
| Corrective Action:              |   | Date: |                 |
| Type: Horizontal Heater Treater | # 1   |       |                 |
| Comment:                        |   |       |                 |
| Corrective Action:              |   | Date: |                 |
| Type: Bird Protectors           | #   |       |                 |
| Comment:                        |   |       |                 |
| Corrective Action:              |   | Date: |                 |
| Type: Gas Meter Run             | # 1   |       |                 |
| Comment:                        |   |       |                 |
| Corrective Action:              |   | Date: |                 |

**Tanks and Berms:**

|          |   |          |      |         |        |  |
|----------|---|----------|------|---------|--------|--|
| Contents | # | Capacity | Type | Tank ID | SE GPS |  |
|----------|---|----------|------|---------|--------|--|

|                    |          |                     |                     |             |   |       |
|--------------------|----------|---------------------|---------------------|-------------|---|-------|
| PRODUCED WATER     | 1        | 400 BBLs            | HEATED STEEL AST    |             | , |       |
| Comment:           |          |                     |                     |             |   |       |
| Corrective Action: |          |                     |                     |             |   | Date: |
| <b>Paint</b>       |          |                     |                     |             |   |       |
| Condition          | Adequate |                     |                     |             |   |       |
| Other (Content)    |          |                     |                     |             |   |       |
| Other (Capacity)   |          |                     |                     |             |   |       |
| Other (Type)       |          |                     |                     |             |   |       |
| <b>Berms</b>       |          |                     |                     |             |   |       |
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |   |       |
| Metal              | Adequate |                     |                     | Adequate    |   |       |
| Comment:           |          |                     |                     |             |   |       |
| Corrective Action: |          |                     |                     |             |   | Date: |
| <b>Venting:</b>    |          |                     |                     |             |   |       |
| Yes/No             | NO       |                     |                     |             |   |       |
| Comment:           |          |                     |                     |             |   |       |
| Corrective Action: |          |                     |                     |             |   | Date: |
| <b>Flaring:</b>    |          |                     |                     |             |   |       |
| Type               |          |                     |                     |             |   |       |
| Comment:           |          |                     |                     |             |   |       |
| Corrective Action: |          |                     |                     |             |   | Date: |

| Inspected Facilities   |        |       |      |             |           |         |    |               |    |
|--|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID:   | 260476 | Type: | WELL | API Number: | 081-07062 | Status: | PR | Insp. Status: | SI |
| Idle Well  |        |       |      |             |           |         |    |               |    |
| Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned      Reminder: _____ |        |       |      |             |           |         |    |               |    |
| Comment: _____   |        |       |      |             |           |         |    |               |    |
| Corrective Action: _____      Date: _____  |        |       |      |             |           |         |    |               |    |

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Berms            |                 |                         |                       |               |                          |         |
| Compaction       |                 |                         |                       |               |                          |         |

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description       | URL   |
|--------------|-------------------|---|
| 689805706    | Inspection Photos | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5423185">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5423185</a> |