

Inspection Photos

Location Name: LARAMIE ENERGY LLC Currier BCU /1K Pad

Location ID: 312707



Photo #3741 from entrance to location.



Photo #3742 from entrance to location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: LARAMIE ENERGY LLC Carrier BCU /1K Pad

Location ID: 312707



Photo #3743 No battery sign located at the tank battery.



Photo #3749 Multiple places with stained soil outside of containment.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: LARAMIE ENERGY LLC Currier BCU /1K Pad

Location ID: 312707



Photo #3744 Location lacks stabilization.



Photo #3745 Location lacks stabilization.

Inspection Photos

Location Name: LARAMIE ENERGY LLC Currier BCU /1K Pad

Location ID: 312707



Photo #3746 No form of tracking BMP located at entrance to location.



Photo #3750 No chemical BMP located at chemical tank. Stained soils under chemical tank.