

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



OGCC RECEPTION Receive Date: 09/28/2020 Document Number: 402498381

Off-Location Flowline

The Flowline Report, Form 44, shall be submitted to register, report realignment, report removal from service, provide pre-abandonment notices, or report abandonment of Off-Location Flowlines, Flowline Systems, Produced Water Transfer Systems, or Crude Oil Transfer Lines or Systems as required by the 1100 Series Rules. The Form 44 shall also be submitted to register, report realignment, or report abandonment of Domestic Taps, and to report Grade 1 Gas Leaks from Flowlines per Rules 610 and

Operator Information

OGCC Operator Number: 10646 Contact Person: Nathan Bennett Company Name: AXIS EXPLORATION LLC Phone: (720) 354-4616 Address: 370 17TH ST SUITE 5300 Email: nbennett@extractionog.com City: DENVER State: CO Zip: 80202 Is the Operator a Tier One member of the Utility Notification Center of Colorado (CO811) that participates in Colorado's One Call notification system? Yes [X] No []

OFF LOCATION FLOWLINE

FLOWLINE ENDPOINT LOCATION IDENTIFICATION

Location ID: 320745 Location Type: Production Facilities Name: COLUMBINE-STATE-64S64W Number: 16SESE County: ARAPAHOE Qtr: SESE Section: 16 Township: 4S Range: 64W Meridian: 6 Latitude: 39.696083 Longitude: -104.547863

Description of Corrosion Protection

Axis's corrosion procedures are detailed in its Flowline Management SOP. Coating materials will be used that minimize internal and external corrosion, such as internally coated pipe or stainless steel for water service, and externally coated FBE on all buried steel pipe. If flowlines are repaired due to corrosion, Axis will investigate the failure, promptly respond with the appropriate remedial actions and determine the root cause and apply corrective actions as necessary. Axis retains records of its chemical program in the form of Failure Analysis Reports, records of chemical invoices and chemical delivery.

Description of Integrity Management Program

Axis's integrity management program is detailed in its Flowline Management SOP, which covers flowline installation, operation, maintenance, inspection, testing, and repairs. Prior to beginning any project involving flowlines, Axis ensures the project plans, flowline installation, flowline maintenance (including repairs) and all flowline inspection and testing projects meet the requirements of the Flowline Management SOP. All pressure tests on flowlines will be conducted by an independent, third party qualified to do such testing. Precautions shall be taken to protect employees and the general public.

Description of the construction method used for public by-ways, road crossings, sensitive wildlife habitats, sensitive areas, and natural and manmade watercourses (i.e., open trench, bored and cased, or bored only), if applicable.

Axis acquired this flowline and associated well and facilities. The project was originally developed in the early-1980s. As such, Axis is unable to describe the construction methods used to cross any natural watercourse present.

FLOWLINE FACILITY INFORMATION

Flowline Facility ID: 460546 Flowline Type: Wellhead Line Action Type: Abandonment Verification

OFF LOCATION FLOWLINE REGISTRATION

Equipment at End Point Riser: Separator

Flowline Start Point Location Identification

Location ID: 320745 Location Type: Well Site
Name: COLUMBINE-STATE-64S64W Number: 16SESE
County: ARAPAHOE No Location ID
Qtr Qtr: SESE Section: 16 Township: 4S Range: 64W Meridian: 6
Latitude: 39.696083 Longitude: -104.547863

Equipment at Start Point Riser: Well

Flowline Description and Testing

Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches) 2.375
Bedding Material: Native Materials Date Construction Completed: 10/19/1983
Maximum Anticipated Operating Pressure (PSI): 76 Testing PSI: 76
Test Date: 04/23/2018

OFF LOCATION FLOWLINE Abandonment Verification

Date: 09/22/2020

Abandonment Verification

The abandoned Off-Location Flowline was located within the jurisdiction(s) of the following local government(s).

Jurisdiction	County	Municipality
County	ARAPAHOE	

Description of Abandonment Verification:

The subject flowline was removed in the following manner - bell-holes were dug along the flowline corridor. The flowline was cut in sections and pulled from the bell-holes. A total of 722' of 2-3/8" steel flowline (buried ~3' deep) was removed. Bell-holes were backfilled and graded.

OPERATOR COMMENTS AND SUBMITTAL

Comments This Form 44 is being filed for an off-location flowline abandonment. Please note, the flowline was removed in its entirety (NOT abandoned in place). No disturbance occurred between OHWM of the natural watercourse commonly known as "Kiowa Creek".

00506858FL
- Previously serviced the Columbine State #1 well (05-005-06858).
- Updated GIS SHAPEFILE attached.
- Recent PRESSURE TEST attached.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct and complete.

Signed: _____ Date: 09/28/2020 Email: nbennett@extractionog.com

Print Name: Nathan Bennett Title: Regulatory Supervisor

Based on the information provided herein, this Flowline Report complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: _____ Director of COGCC Date: _____

Conditions of Approval

COA Type

Description

--	--

Attachment Check List

Att Doc Num

Name

402498475	OFF-LOCATION FLOWLINE GIS DATA
402498477	PRESSURE TEST

Total Attach: 2 Files

General Comments

User Group

Comment

Comment Date

		Stamp Upon Approval

Total: 0 comment(s)

