

# Inspection Photos

5/6/2021

Operator: SG INTERESTS I LTD - 77330

Location ID: 418697

Gunnison County, CO

Aaron Trujillo  
NW Reclamation Specialist  
COGCC

Inspection Photos  
Operator Name: SG INTERESTS I LTD - 77330  
Location ID: 418697



**Photo 1:** Photo taken from the east end of the Location, facing north. Construction activities to address stormwater issues observed to be in process at time of inspection. Photo shows ditch and armoring in process of being constructed to manage runoff. Armoring has been constructed with different sized aggregate and lined with geotextile.

Inspection Photos  
Operator Name: SG INTERESTS I LTD - 77330  
Location ID: 418697



**Photo 2:** See comments under photo 1.

Inspection Photos  
Operator Name: SG INTERESTS I LTD - 77330  
Location ID: 418697



**Photo 3:** See comments under photo 1.

Inspection Photos  
Operator Name: SG INTERESTS I LTD - 77330  
Location ID: 418697



**Photo 4:** Photo taken from the cut slopes on the north end of the Location. Photo shows the sloughing slope observed in previous inspections has been repaired and a French drain system has been install. Slopes still requiring stabilization control measures and revegetation.

Inspection Photos  
Operator Name: SG INTERESTS I LTD - 77330  
Location ID: 418697



**Photo 5:** See comments under photo 4.

Inspection Photos  
Operator Name: SG INTERESTS I LTD - 77330  
Location ID: 418697



**Photo 6:** Photo taken from the north of the Location, facing east. Construction activities to address stormwater issues observed to be in process at time of inspection. Photo shows ditch being constructed to manage runoff.

Inspection Photos  
Operator Name: SG INTERESTS I LTD - 77330  
Location ID: 418697



**Photo 7:** Photo taken from the north of the Location, facing west. Construction activities to address stormwater issues observed to be in process at time of inspection. Photo shows ditch being constructed to manage runoff.

Inspection Photos  
Operator Name: SG INTERESTS I LTD - 77330  
Location ID: 418697



**Photo 8:** See comments under photo 7.

Inspection Photos  
Operator Name: SG INTERESTS I LTD - 77330  
Location ID: 418697



**Photo 9:** Photo taken from the northwest corner of the Location, facing north. Photo shows Operator has installed armoring along section of the ditch that travels downslope. Rock used is very large and not properly sized per good engineering practices. Geotextile lining has been placed beneath the riprap.

Inspection Photos  
Operator Name: SG INTERESTS I LTD - 77330  
Location ID: 418697



**Photo 10:** Photo taken from the west end of the Location, facing northeast. Construction activities to address stormwater issues observed to be in process at time of inspection. Operator on site indicated control measures such as a sediment trap or pond is being considered at the end of the ditches to allow for appropriate stormwater discharge from the disturbance area.

Inspection Photos  
Operator Name: SG INTERESTS I LTD - 77330  
Location ID: 418697



**Photo 11:** Photo taken from the southwest end of the Location, facing east. Photo shows Operator has installed silt fence as a temporary measure to manage runoff.

Inspection Photos  
Operator Name: SG INTERESTS I LTD - 77330  
Location ID: 418697



**Photo 12:** See comments under photo 11. Operator on site stated that control measures to stabilize soils and additional revegetation activities are planned.

Inspection Photos  
Operator Name: SG INTERESTS I LTD - 77330  
Location ID: 418697



**Photo 13:** Photo taken from the ditch on the west end of the former pad, facing north. Photo shows inlet to a slope drain that has been installed at end of the Ditch.

Inspection Photos  
Operator Name: SG INTERESTS I LTD - 77330  
Location ID: 418697



**Photo 14:** See comments under photo 13.

Inspection Photos  
Operator Name: SG INTERESTS I LTD - 77330  
Location ID: 418697



**Photo 15:** Continued from photo 13. Photo shows slope drain and the outlet. Unclear if the slope drain is sufficiently secured.

Inspection Photos  
Operator Name: SG INTERESTS I LTD - 77330  
Location ID: 418697



**Photo 16:** Continued from photo 13. Photo shows slope drain has not been constructed with an appropriate outlet in accordance with good engineering practices.

Inspection Photos  
Operator Name: SG INTERESTS I LTD - 77330  
Location ID: 418697



**Photo 17:** Photo shows silt fence along the western areas of the Location's disturbance.

Inspection Photos  
Operator Name: SG INTERESTS I LTD - 77330  
Location ID: 418697



**Photo 18:** Photo taken from the south end of the Location. Operator has installed a drain/culvert that travels beneath the soils from the pad to the slopes. Drain has not been constructed with an appropriate outlet.