

Inspection Photos

API: 009-06215

Operator: SOVEREIGN OPERATING COMPANY

Inspection Date: 5/5/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos



Photo 1. Facing northeast toward the area where the tank battery was location. This area does not have crop establishment and soils will need to be reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06215 | Date: 5/5/2021

Inspection Photos



Photo 2. Facing southeast toward the area where the tank battery was location. This area does not have crop establishment and soils will need to be reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06215 | Date: 5/5/2021

Inspection Photos



Photo 3. Facing north along the former access road. There are areas along the access road where the crop is not establishing very well.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06215 | Date: 5/5/2021

Inspection Photos



Photo 4. Facing north at the location. There is no crop growth at this area of the location approximately 120'x80'.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06215 | Date: 5/5/2021

Inspection Photos



Photo 5. Facing south at the location. There is no crop growth at this area of the location approximately 120'x80'.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06215 | Date: 5/5/2021

Inspection Photos



Photo 6. Facing toward the surrounding croipland.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06215 | Date: 5/5/2021