

Inspection Photos

API: 009-06322

Operator: DOVER ATWOOD CORPORATION

Inspection Date: 5/5/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos



Photo 1. Facing southeast toward the location. The location has been recontoured and decompacted. All equipment has been removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06322 | Date: 5/5/2021

Inspection Photos



Photo 2. Facing southeast toward the location. The location has been recontoured and decompacted. It is unknown if seeding occurred. No desirable vegetation germination was observed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06322 | Date: 5/5/2021

Inspection Photos



Photo 3. View of groundcover. The green vegetation is undesirable weeds which will need to be controlled.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06322 | Date: 5/5/2021

Inspection Photos



Photo 4. Facing west toward the surrounding undisturbed pasture which consists of native desirable vegetation cover.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06322 | Date: 5/5/2021