

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/30/2021

Submitted Date:

04/30/2021

Document Number:

700702665

**FIELD INSPECTION FORM**

Loc ID 335209 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: PO BOX 370

City: PARACHUTE State: CO Zip: 81635

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

17 Number of Comments

4 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
291978	WELL	PR	10/01/2012	GW	045-14577	JOLLEY 21-3D	PR
291981	WELL	PR	09/10/2008	GW	045-14574	JOLLEY 21-2D	PR
300760	WELL	PR	01/01/2021	GW	045-17996	Jolley KP 322-21	PR
300761	WELL	PR	02/01/2020	GW	045-17997	JOLLEY KP 522-21	PR
300762	WELL	PR	02/01/2020	GW	045-17998	Jolley KP 32-21	PR
300763	WELL	PR	02/01/2020	GW	045-17999	Jolley KP 332-21	PR
300764	WELL	PR	02/01/2020	GW	045-18000	Jolley KP 432-21	PR
300765	WELL	PR	01/17/2012	GW	045-18001	Jolley KP 532-21	PR

**General Comment:****COGCC Inspection Report Summary**

On Friday 4/30/2021 at approximately 1200, I, Inspector Scott Ramsey, conducted a routine inspection at TEP KP 22-21, at Location # 335209 in Garfield county Colorado.

While there, I observed normal production operations. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat and Wildlife Management Area. Also location is within or in close proximity to the 411 water protection area. Operator (TERRA) has provided there Piceance Basin Storm water Manual of BMP's (SC-4) for tracking pad, there is no evidence of a tracking pad at time of inspection.

During this inspection the following compliance issues were observed:

1. Location shows signs of lack of stabilization/compaction
2. Random debris
3. No battery signage
4. Unused equipment (chemical tank)

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location			
<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action	L	Date:	
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:	No battery signage		
Corrective Action:	Comply with rule 605.e	Date:	05/31/2021
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	911		
Corrective Action:		Date:	
<b>Good Housekeeping:</b>			
Type	DEBRIS		
Comment:	Random debris		
Corrective Action:	remove all debris	Date:	05/31/2021
Type	UNUSED EQUIPMENT		
Comment:	Unused equipment (chemical tank)		
Corrective Action:	remove unused equipment	Date:	05/31/2021
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Equipment:</b>			
Type: Horizontal Heated Separator	# 8		corrective date
Comment:			
Corrective Action:		Date:	

Type: Horizontal Heater Treater	# 1		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 8		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 9		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 3		
Comment:	Two chemical tanks at well heads and one at meter buildings (unused equipment) all are in plastic containments		
Corrective Action:			Date:
Type: Deadman # & Marked	# 3		
Comment:			
Corrective Action:			Date:
Type: Compressor	# 2		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 8		
Comment:	Braden heads have telemetry for monitoring.		
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLs	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	4	300 BBLs	HEATED STEEL AST		,
Comment:	Two tanks are NOT heated				

Corrective Action:		Date:	
<b>Paint</b>			
Condition	Adequate		
Other (Content)			
Other (Capacity)			
Other (Type)			
<b>Berms</b>			
Type	Capacity	Permeability (Wall)	Permeability (Base)
Metal	Adequate	Walls Sufficient	Base Sufficient
Comment:			
Corrective Action:			Date:
<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:			Date:
<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	291978	Type:	WELL	API Number:	045-14577	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	291981	Type:	WELL	API Number:	045-14574	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	300760	Type:	WELL	API Number:	045-17996	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	300761	Type:	WELL	API Number:	045-17997	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	300762	Type:	WELL	API Number:	045-17998	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	300763	Type:	WELL	API Number:	045-17999	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	300764	Type:	WELL	API Number:	045-18000	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	300765	Type:	WELL	API Number:	045-18001	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:						Date:			

--

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Check Dams				
Ditches						
		Ditches				
Compaction	Fail					
Berms						
		Culverts				

Comment: This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat and Wildlife Management Area. Also location is within or in close proximity to the 411 water protection area. Operator (TERRA) has provided there Piceance Basin Storm water Manual of BMP's (SC-4) for tracking pad, there is no evidence of a tracking pad at time of inspection.  
1. Location shows signs of lack of stabilization/compaction

Corrective Action: **Install or repair required BMPs**

Date: 05/31/2021

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402677264	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5418459">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5418459</a>
700702672	photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5418452">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5418452</a>