

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



OGCC RECEPTION Receive Date: 12/03/2020 Document Number: 402545339

Off-Location Flowline

The Flowline Report, Form 44, shall be submitted to register, report realignment, report removal from service, provide pre-abandonment notices, or report abandonment of Off-Location Flowlines, Flowline Systems, Produced Water Transfer Systems, or Crude Oil Transfer Lines or Systems as required by the 1100 Series Rules. The Form 44 shall also be submitted to register, report realignment, or report abandonment of Domestic Taps, and to report Grade 1 Gas Leaks from Flowlines per Rules 610 and 611.

Operator Information

OGCC Operator Number: 10646 Contact Person: Nathan Bennett Company Name: AXIS EXPLORATION LLC Phone: (720) 354-4616 Address: 370 17TH ST SUITE 5200 Email: nbennett@extractionog.com City: DENVER State: CO Zip: 80202 Is the Operator a Tier One member of the Utility Notification Center of Colorado (CO811) that participates in Colorado's One Call notification system? Yes [X] No []

OFF LOCATION FLOWLINE

FLOWLINE ENDPOINT LOCATION IDENTIFICATION

Location ID: 460776 Location Type: Production Facilities Name: Sabo 22-19 4 TB Number: County: ELBERT Qtr: SENW Section: 19 Township: 6S Range: 62W Meridian: 6 Latitude: 39.519922 Longitude: -104.367047

Description of Corrosion Protection

Axis's corrosion procedures are detailed in its Flowline Management SOP. Coating materials will be used that minimize internal and external corrosion, such as internally coated pipe or stainless steel for water service, and externally coated FBE on all buried steel pipe. If flowlines are repaired due to corrosion, Axis will investigate the failure, promptly respond with the appropriate remedial actions and determine the root cause and apply corrective actions as necessary. Axis retains records of its chemical program in the form of Failure Analysis Reports, records of chemical invoices and chemical delivery.

Description of Integrity Management Program

Axis's integrity management program is detailed in its Flowline Management SOP, which covers flowline installation, operation, maintenance, inspection, testing, and repairs. Prior to beginning any project involving flowlines, Axis ensures the project plans, flowline installation, flowline maintenance (including repairs) and all flowline inspection and testing projects meet the requirements of the Flowline Management SOP. All pressure tests on flowlines will be conducted by an independent, third party qualified to do such testing. Precautions shall be taken to protect employees and the general public.

Description of the construction method used for public by-ways, road crossings, sensitive wildlife habitats, sensitive areas, and natural and manmade watercourses (i.e., open trench, bored and cased, or bored only), if applicable.

N/A

FLOWLINE FACILITY INFORMATION

Flowline Facility ID: 461046 Flowline Type: Wellhead Line Action Type: Out of Service

OFF LOCATION FLOWLINE REGISTRATION

Equipment at End Point Riser: Separator

Flowline Start Point Location Identification

Location ID: 322205 Location Type: Well Site
Name: SABO 22-19-66S62W Number: 19SENW
County: ELBERT No Location ID
Qtr Qtr: SENW Section: 19 Township: 6S Range: 62W Meridian: 6
Latitude: 39.515100 Longitude: -104.378470

Equipment at Start Point Riser: Well

Flowline Description and Testing

Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches) 2.375
Bedding Material: Native Materials Date Construction Completed: 12/28/1988
Maximum Anticipated Operating Pressure (PSI): 31 Testing PSI: 31
Test Date: 04/30/2018

OFF LOCATION FLOWLINE Out of Service

Date: 10/16/2020

Entire Line Removal

Partial Line Removal

Description of Out of Service:

Flowline was OOSLAT on 10/16/2020. Prior to applying locks and tags, the flowline was flushed and purged.

OPERATOR COMMENTS AND SUBMITTAL

Comments

This Form 44 is being submitted for OOSLAT of the subject flowline. The flowline was OOSLAT on 10/16/2020.
03906596FL
- Recent PRESSURE TEST attached.
- GIS shapefile attached.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct and complete.

Signed: _____ Date: 12/03/2020 Email: nbennett@extractionog.com

Print Name: Nathan Bennett Title: Regulatory Supervisor

Based on the information provided herein, this Flowline Report complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved:  Director of COGCC Date: 5/10/2021

Conditions of Approval

COA Type

Description

--	--

Attachment Check List

Att Doc Num

Name

402545339	Form44 Submitted
402545351	PRESSURE TEST
402545352	OFF-LOCATION FLOWLINE GEODATABASE SHP

Total Attach: 3 Files

General Comments

User Group

Comment

Comment Date

		Stamp Upon Approval

Total: 0 comment(s)