

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/06/2021

Submitted Date:

05/10/2021

Document Number:

696900155**FIELD INSPECTION FORM**Loc ID 319636 Inspector Name: CHESSON, BOB On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 76840Name of Operator: SCHNEIDER ENERGY SERVICES INCAddress: P O BOX 889City: FORT MORGAN State: CO Zip: 80701**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Axelson, John		john.axelson@state.co.us	
Medina, Justin		justin.medina@state.co.us	
Gomez, Jason		jason.gomez@state.co.us	
Schneider, Jeff	970-867-9437/ (214) 244-3819	jeff@schneiderenergy.com	

General Comment:

Inspection for spill #402679995. Spill location is at the tank battery (sw of well [Location Number 479956]). Inspected on 5/7/21. Fluid removal from oil tank underway. Based on fluid records and recovery, the release is estimated to have been approximately 160 BBLs of fluid with approximately 50 BBLs recovered. Work to clean-up the surface spillage underway. Vert. extent appears to be under 12 inches based on observations. Fluid breached the oil tank containment berm on the ne side and flowed down the slope toward the lease road to the Cordes #3 wellhead. Spill flowed in a narrow path to the sse toward the wellhead.

See attached inspection photos.

Environmental**Spills/Releases:**

Type of Spill: OIL

Estimated Spill Volume: 160

Comment: Fluid breached the TB berm and flowed to the NNE. Combination of PW and oil. See spill report #402579995.

Corrective Action: Remove impacted spoils and conduct clean-up confirmation sampling. Clean-up actions with confirmation sampling must be documented on a supplemental Form 19 within 90 days of the initial spill/release report.

Date: 08/03/2021

Reportable: YES

GPS: Lat

Long

Proximity to Surface Water:

Depth to Ground Water:

Water Well Complaint:

Lat

Long

DWR Receipt Num:

Owner Name:

GPS :

Field Parameters:

Sample Location:

Comment:

COGCC Comments

Comment

User

Date

Inspection for spill #402679995. Spill location is at the tank battery (sw of well [Location Nnumber 479956]). Inspected on 5/7/21. Fluid removal from oil tank underway. Based on fluid records and recovery, the release is estimated to have been approximately 160 BBLs of fluid with approximately 50 BBLs recovered. Work to clean-up the surface spillage underway. Vert. extent appears to be under 12 inches based on observations. Fluid breached the oil tank containment berm on the ne side and flowed down the slope toward the lease road to the Cordes #3 wellhead. Spill flowed in a narrow path to the sse toward the wellhead.

chessonr

05/10/2021

See attached inspection photos.

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696900156	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5424527