

## Inspection Photos

Location Name: Silver Spur Minerals 35-2H

API: 05-057-06490

Date: May 6, 2021



Location sign off of Hwy 14.



Well sign.



## Inspection Photos

Location Name: Silver Spur Minerals 35-2H

API: 05-057-06490

Date: May 6, 2021



Equipment stored on Location.



Equipment stored on Location.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Location Name: Silver Spur Minerals 35-2H

API: 05-057-06490

Date: May 6, 2021



Propane tank not labeled or placard.



Tank signage, labels, and placards are illegible.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

Location Name: Silver Spur Minerals 35-2H

API: 05-057-06490

Date: May 6, 2021



Tank 0030, staining beneath hammer unions.



Tank 0030, staining beneath hammer unions.





## Inspection Photos

Location Name: Silver Spur Minerals 35-2H

API: 05-057-06490

Date: May 6, 2021



Staining from on-going gas leak/vent and condensate around wellhead.



Staining from on-going gas leak/vent and condensate around wellhead.

## Inspection Photos

Location Name: Silver Spur Minerals 35-2H

API: 05-057-06490

Date: May 6, 2021



Valve in red circle is where gas was venting.

Valve is where gas was venting.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources