

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/06/2021

Submitted Date:

05/10/2021

Document Number:

696900155

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: CHESSON, BOB On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 76840
Name of Operator: SCHNEIDER ENERGY SERVICES INC
Address: P O BOX 889
City: FORT MORGAN State: CO Zip: 80701

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 3 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Medina, Justin		justin.medina@state.co.us	
Axelson, John		john.axelson@state.co.us	
Gomez, Jason		jason.gomez@state.co.us	
Schneider, Jeff	970-867-9437/ (214) 244-3819	jeff@schneiderenergy.com	

General Comment:

Inspection for spill #402679995. Spill location is at the tank battery (sw of well [Location Nnumber 479956]). Inspected on 5/7/21. Fluid removal from oil tank underway. Based on fluid records and recovery, the release is estimated to have been approximately 160 BBLs of fluid with approximately 50 BBLs recovered. Work to clean-up the surface spillage underway. Vert. extent appears to be under 12 inches based on observations. Fluid breached the oil tank containment berm on the ne side and flowed down the slope toward the lease road to the Cordes #3 wellhead. Spill flowed in a narrow path to the sse toward the wellhead.

See attached inspection photos.

Environmental

Spills/Releases:

Type of Spill: OIL Estimated Spill Volume: 160

Comment: Fluid breached the TB berm and flowed to the NNE. Combination of PW and oil. See spill report #402579995.

Corrective Action: Remove impacted spoils and conduct clean-up confirmation sampling. Clean-up actions with confirmation sampling must be documented on a supplemental Form 19 within 90 days of the initial spill/release report. Date: 08/03/2021

Reportable: YES GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

COGCC Comments

Comment	User	Date
Inspection for spill #402679995. Spill location is at the tank battery (sw of well [Location Nnumber 479956]). Inspected on 5/7/21. Fluid removal from oil tank underway. Based on fluid records and recovery, the release is estimated to have been approximately 160 BBLs of fluid with approximately 50 BBLs recovered. Work to clean-up the surface spillage underway. Vert. extent appears to be under 12 inches based on observations. Fluid breached the oil tank containment berm on the ne side and flowed down the slope toward the lease road to the Cordes #3 wellhead. Spill flowed in a narrow path to the sse toward the wellhead. See attached inspection photos.	chessonr	05/10/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402684139	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5424532
696900156	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5424527