

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/11/2021

Submitted Date:

05/12/2021

Document Number:

701500691

FIELD INSPECTION FORM

Loc ID 398876 Inspector Name: Moran, Rick On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 76950
Name of Operator: SCHUMACHER* JOHN
Address: _____
City: DENVER State: CO Zip: 80203

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

7 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Hickey, Mike		michael.hickey@state.co.us	
Thompson, Bud		BLThomps@BLM.gov	
Chollett, Shannon		shannon.chollett@state.co.us	
Heil, John		john.heil@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
232299	WELL	DA	05/01/1962	DA	103-40088	USA--COLO 06412 2-G	DA

General Comment:

Routine well inspection of an abandon well that is venting gas.

Well is 270' from the nearest residence, 840' from a church sponsored school, and 1200' from Rangely's municipal water plant. The COGCC database shows the location is on BLM surface & minerals. The Rio Blanco county records shows the well is on private surface.

40.086626, -108.776513 Database coordinate.
40.08734, -108.77666 Actual coordinate.

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Well marker with lettering "G.L. HELMKE - 2G" & "LOT - 11"		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input type="text"/>	Date:	
Corrective Action:	<input type="text"/>	Date:	

Good Housekeeping:

Type	OTHER		
Comment:	4 ft tall asphalt road pile debris. Location is next to Colorado State Hwy 139.		
Corrective Action:		Date:	

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No	YES		
Comment:	Gas odor detected within 10' of well. Audible fluid movement heard next to well. See video attachment.		
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 232299 Type: WELL API Number: 103-40088 Status: DA Insp. Status: DA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other						Mature vegetation.

Comment: No significant soil migration, erosion or soil movement on location.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701500692	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5426390
701500693	Audible fluid movement video	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5426391