

Inspection Photos

5/11/2021

Operator: LARAMIE ENERGY LLC - 10433

Location ID: 335091

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335091



Photo 1: Photo taken from the west end of the production area, facing north. Photos 1-4 provide an overview of the Location from north, northeast, southeast to south.

Photo 2: See comments under photo 1.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335091



Photo 3: See comments under photo 1.



Photo 4: See comments under photo 1.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335091



Photo 5: Photo taken from the production area, facing north.. Photo shows control measures to stabilize the production area are missing or insufficient.



Photo 6: Photo taken from the production area, facing north.. Photo shows control measures to stabilize the production area are missing or insufficient.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335091



Photo 7: Photo taken from the production area, facing east. Operator has installed wattles along the base and upper portions of the cut slope; no other control measures were observed to be used in conjunction with the wattles on the slopes. Photo shows areas where erosion on the cut slopes have covered multiple sections of wattles. BMPs to stabilize/protect remain missing or insufficient.



Photo 8: Photo shows wattles along base of cut slope; wattles do not appear to have been properly trenched and backfilled in accordance with good engineering practices.

Inspection Photos

Operator Name: LARAMIE ENERGY LLC - 10433

Location ID: 335091



Photo 9: Photo shows areas where erosion on the cut slopes have covered multiple sections of wattles.



Photo 10: Photo taken from the cut slope on the east end of the Location, facing north. Operator has installed wattles along the base and upper portions of the cut slope; no other control measures were observed to be used in conjunction with the wattles on the slopes. BMPs to stabilize/protect remain missing or insufficient.

Inspection Photos

Operator Name: LARAMIE ENERGY LLC - 10433

Location ID: 335091



Photo 11: Photo taken from the access road, facing southwest. Photo shows BMPs to stabilize production areas/access road and to prevent off-location sediment transport during wet conditions are missing or insufficient



Photo 12: Photo taken from the access road entrance, facing southwest. Photo shows BMPs to stabilize production areas/access road and to prevent off-location sediment transport during wet conditions are missing or insufficient

Inspection Photos

Operator Name: LARAMIE ENERGY LLC - 10433

Location ID: 335091



Photo 13: Photo taken from the access road entrance, facing south. Photo shows BMPs to stabilize production areas/access road and to prevent off-location sediment transport during wet conditions are missing or insufficient