

Inspection Photos

Location Name: CAERUS PICEANCE LLC WALLING-68S96W /1NWSE

Location ID: 334062



Photo #3785 from entrance to location.



Photo #3786 from entrance to location.

Inspection Photos

Location Name: CAERUS PICEANCE LLC WALLING-68S96W /1NWSE

Location ID: 334062



Photo #3787 Location lacks stabilization.



Photo #3549 from inspection #699802949 inspection conducted on 4/19/21.

Inspection Photos

Location Name: CAERUS PICEANCE LLC WALLING-68S96W /1NWSE

Location ID: 334062



Photo #3788 No form of tracking BMP at entrance to location.



Photo #3550 from inspection #699802949 inspection conducted on 4/19/21

Inspection Photos

Location Name: CAERUS PICEANCE LLC WALLING-68S96W /1NWSE

Location ID: 334062



Photo #3789 Sediment has been transported off of location.



Photo #3545 from inspection #699802949 inspection conducted on 4/19/21.

Inspection Photos

Location Name: CAERUS PICEANCE LLC WALLING-68S96W /1NWSE

Location ID: 334062



Photo #3790 Sediment is choking off vegetation.



Photo #3546 from inspection #699802949 inspection conducted on 4/19/21.

Inspection Photos

Location Name: CAERUS PICEANCE LLC WALLING-68S96W /1NWSE

Location ID: 334062



Photo #3791 Sediment has been transported off location.

