

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/13/2021

Submitted Date:

05/13/2021

Document Number:

690007461

FIELD INSPECTION FORMLoc ID 405923 Inspector Name: Carlile, Craig On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10633

Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC

Address: 1801 CALIFORNIA STREET #2500

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

3 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|-------|----------------------------------|---------|
| , | | cogcc.inspections@crestonepr.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|--------------|--------|-------------|------------|---------|------------------------------------|-------------|
| 456894 | TANK BATTERY | AC | 08/27/2018 | | - | BC 2-4-20,2-8-20 TB | AO |
| 456895 | TANK BATTERY | AC | 08/27/2018 | | - | BC 13-20,4-20,14-20,24-20,23-20 TB | AO |

General Comment:

LocationOverall Good: ☒**Signs/Marker:**

| | | | |
|--------------------|----------------------|-------|--|
| Type | TANK LABELS/PLACARDS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | BATTERY | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

| | | | |
|--------------------|--|-------|--|
| Comment: | | | |
| Corrective Action: | | Date: | |

Overall Good: ☒**Spills:**

| | | | | |
|------|------|--------|--|--|
| Type | Area | Volume | | |
|------|------|--------|--|--|

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

| | | | |
|-----------------------------------|-----|-------|-----------------|
| Type: Bird Protectors | # 4 | | corrective date |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Horizontal Heated Separator | # 3 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Emission Control Device | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| | | | | | |
|--------------------|---|----------|-----------|---------|-----------------------|
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| CRUDE OIL | 1 | 300 BBLS | STEEL AST | | 40.205940,-104.826860 |
| Comment: | | | | | |
| Corrective Action: | | Date: | | | |

Paint

| | | | | | |
|-----------------|--|--|--|--|--|
| Condition | | | | | |
| Other (Content) | | | | | |

| | | | | | | |
|--|----------|---------------------|---------------------|-------------|------------------------|-------|
| Other (Capacity) | | | | | | |
| Other (Type) | | | | | | |
| <u>Berms</u> | | | | | | |
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | | |
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate | | |
| Comment: | | | | | | |
| Corrective Action: | | | | | | Date: |
| Contents | # | Capacity | Type | Tank ID | SE GPS | |
| PRODUCED WATER | 1 | OTHER | PBV FIBERGLASS | | 40.205940,-104.826860 | |
| Comment: | | | | | | |
| Corrective Action: | | | | | | Date: |
| <u>Paint</u> | | | | | | |
| Condition | | | | | | |
| Other (Content) | | | | | | |
| Other (Capacity) 150 Bbl | | | | | | |
| Other (Type) | | | | | | |
| <u>Berms</u> | | | | | | |
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | | |
| | | | | | | |
| Comment: Shared with condensate tank. | | | | | | |
| Corrective Action: | | | | | | Date: |
| Contents | # | Capacity | Type | Tank ID | SE GPS | |
| PRODUCED WATER | 2 | OTHER | PBV FIBERGLASS | | -40.205830,-104.806600 | |
| Comment: | | | | | | |
| Corrective Action: | | | | | | Date: |
| <u>Paint</u> | | | | | | |
| Condition | | | | | | |
| Other (Content) | | | | | | |
| Other (Capacity) 110 Bbl | | | | | | |
| Other (Type) | | | | | | |
| <u>Berms</u> | | | | | | |
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | | |
| | | | | | | |
| Comment: Shared with condensate tanks. | | | | | | |
| Corrective Action: | | | | | | Date: |
| Contents | # | Capacity | Type | Tank ID | SE GPS | |
| CRUDE OIL | 2 | 300 BBLS | STEEL AST | | 40.205830,-104.806600 | |
| Comment: | | | | | | |
| Corrective Action: | | | | | | Date: |
| <u>Paint</u> | | | | | | |

| | |
|------------------|--|
| Condition | |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| | | | | |
|--------------------|----------|---------------------|---------------------|-------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| | | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Venting:

| | | | |
|--------------------|----|--|-------|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Flaring:

| | | |
|--------------------|-------------------|-------|
| Type | Ignitor/Combustor | |
| Comment: | | |
| Corrective Action: | | Date: |

Inspected Facilities

| | | | | |
|---------------------|------------|---------------|------------|------------------|
| Facility ID: 456894 | Type: TANK | API Number: - | Status: AC | Insp. Status: AO |
|---------------------|------------|---------------|------------|------------------|

| | | | | |
|---------------------|------------|---------------|------------|------------------|
| Facility ID: 456895 | Type: TANK | API Number: - | Status: AC | Insp. Status: AO |
|---------------------|------------|---------------|------------|------------------|

COGCC Comments

| Comment | User | Date |
|---|----------|------------|
| Routine battery inspection. | carlilec | 05/13/2021 |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 690007462 | Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5428227 |