

Inspection Photos
Operator: Catamount
API: 067-08217
Date: 5/10/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the northern project area from the northwestern corner facing eastward. Revegetation is becoming established within the interim reclamation areas with western wheatgrass, crested wheatgrass, and sand dropseed.



Photo 3. View of the western project area from the northwestern corner facing southward.



Photo 4. View of the reference area comprised of pinyon and juniper woodland with understory of black sagebrush, squirreltail, western wheatgrass, and forbs such as penstemon, and phlox.