

Inspection Photos
Operator: Catamount
API: 067-05410
Date: 5/10/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the southern project area from the southeastern corner facing westward. Interim reclamation areas are comprised of cultivated field with young crop vegetation present at this time.



Photo 3. View of the eastern project area from the southeastern corner facing northward.



Photo 4. View of the reference area comprised of cultivated field. Crop species and condition compared to the interim reclamation areas are no apparent at this time due to early vegetative condition.