

# Inspection Photos

API: 061-06376

Operator: BERRY ENERGY INC

Inspection Date: 5/12/2021



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 061-06376 | Date: 5/12/2021

## Inspection Photos



**Photo 1.** Drone aerial photo facing east toward the access road. The access road has not been reclaimed. Arrow points to where the road turns north toward the location. The other road at yellow arrow is a separate road which access an active well site.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06376 | Date: 5/12/2021



## Inspection Photos



**Photo 2.** Facing northeast along the access road which dead ends at the location shown at red arrow.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06376 | Date: 5/12/2021



## Inspection Photos



**Photo 3.** Facing north toward the location which has not been reclaimed. Previous corrective action was not performed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06376 | Date: 5/12/2021



## Inspection Photos



**Photo 4.** Facing south toward the location. The location remains mostly devoid of vegetation growth.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06376 | Date: 5/12/2021



## Inspection Photos



**Photo 5.** Facing southeast toward the surrounding undisturbed pasture which shows a uniform vegetation cover.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06376 | Date: 5/12/2021