

Inspection Photos

API: 061-06397

Operator: BERRY ENERGY INC

Inspection Date: 5/12/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06397 | Date: 5/12/2021

Inspection Photos



Photo 1. Drone aerial photo facing southwest toward the location. Red arrow points to tank battery site. Yellow arrow points to the well site. The vegetation has not re-established in the disturbance area. Reclamation has not been completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06397 | Date: 5/12/2021

Inspection Photos



Photo 2. Close up view of the former battery site. This area remains mostly devoid of vegetation growth. There is no indication that reclamation was performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06397 | Date: 5/12/2021

Inspection Photos



Photo 3. Facing south toward the well site. The location remains mostly devoid of vegetation growth. There is no indication that reclamation was performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06397 | Date: 5/12/2021

Inspection Photos



Photo 4. Facing east toward the well site. The location remains mostly devoid of vegetation growth. There is no indication that reclamation was performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06397 | Date: 5/12/2021

Inspection Photos



Photo 5. Facing northwest at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06397 | Date: 5/12/2021

Inspection Photos




Photo 6. Facing south toward the surrounding undisturbed pasture which shows a uniform vegetation cover.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06397 | Date: 5/12/2021