

Inspection Photos

ID: 150131

Operator: STRACHAN EXPLORATION

Inspection Date: 5/12/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos



Photo 1. Facing southwest toward the Salt Lake unit abandoned facility. The electric utilities and steel shed remain at the location. The location has not been reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 150131 | Date: 5/12/2021

Inspection Photos



Photo 2. Facing northwest toward the location which has not been reclaimed. Previous corrective action was not performed. Arrow points to battery site shown in the following photos.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 150131 | Date: 5/12/2021

Inspection Photos



Photo 3. Drone aerial photo facing east toward the access road. The access road has not been reclaimed. Arrow points to where the road turns north toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 150131 | Date: 5/12/2021

Inspection Photos



Photo 4. Facing northeast along the access road which dead ends at the location shown at red arrow.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 150131 | Date: 5/12/2021

Inspection Photos



Photo 5. Facing north toward the location which has not been reclaimed. Previous corrective action was not performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 150131 | Date: 5/12/2021

Inspection Photos



Photo 6. Facing down toward the location. The location remains mostly devoid of vegetation growth. There is no indication that reclamation was performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 150131 | Date: 5/12/2021

Inspection Photos



Photo 7. Facing north at the location. Fence posts remain around the location shown at red arrow.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 150131 | Date: 5/12/2021

Inspection Photos



Photo 8. Facing north at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 150131 | Date: 5/12/2021

Inspection Photos



Photo 9. Facing down toward the location. The location remains mostly devoid of vegetation growth. There is no indication that reclamation was performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 150131 | Date: 5/12/2021

Inspection Photos



Photo 10. Facing southeast toward the surrounding undisturbed pasture which shows a uniform vegetation cover.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 150131 | Date: 5/12/2021