

Inspection Photos

API: 061-06471

Operator: MARATHON OIL COMPANY

Inspection Date: 5/12/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 061-06471 | Date: 5/12/2021

Inspection Photos



Photo 1. Facing south along the former access road which is still evident.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06471 | Date: 5/12/2021

Inspection Photos



Photo 2. Facing south along the road towards the location. This portion of the former access road is bare of vegetation and has not been reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06471 | Date: 5/12/2021

Inspection Photos



Photo 3. It appears equipment and pipe risers have been removed since the previous inspection. The bare areas of the location need to be reclaimed to re-establish vegetation cover.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06471 | Date: 5/12/2021

Inspection Photos



Photo 4. It appears equipment and pipe risers have been removed since the previous inspection. The bare areas of the location need to be reclaimed to re-establish vegetation cover.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06471 | Date: 5/12/2021

Inspection Photos



Photo 5. Facing northwest overlooking the access road and bare disturbance areas of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06471 | Date: 5/12/2021