

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SPECIALTY RESTAURANTS-67S96W /33SWNW

Location ID: 383330



Photo #3798 from entrance to location.



Photo #3799 from entrance to location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SPECIALTY RESTAURANTS-67S96W /33SWNW

Location ID: 383330



Photo #3802 Location lacks stabilization.



Photo #3150 from inspection #699802767 conducted on 3/15/21.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SPECIALTY RESTAURANTS-67S96W /33SWNW

Location ID: 383330




Photo #3803 Location lacks stabilization.



Photo #3151 from inspection #699802767 conducted on 3/15/21.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SPECIALTY RESTAURANTS-67S96W /33SWNW

Location ID: 383330



Photo #3804 No form of tracking BMP located at the entrance to location.



Photo #3152 from inspection #699802767 conducted on 3/15/21.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SPECIALTY RESTAURANTS-67S96W /33SWNW

Location ID: 383330



Photo #3800 No battery sign located at the tank battery