

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/27/2021

Submitted Date:

05/14/2021

Document Number:

693803039

**FIELD INSPECTION FORM**

Loc ID: 316734 Inspector Name: BROWNING, CHUCK On-Site Inspection:  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 100264  
Name of Operator: XTO ENERGY INC  
Address: 110 W 7TH STREET  
City: FORT WORTH State: TX Zip: 76102

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

8 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector
Labowskie, Steve		steve.labowskie@state.co.us	
Clark, Erin	405-319-3250	erin.k.clark@exxonmobil.com	XTO Piceance and BOPCO Piceance
Dooling, Jessica	(970) 878-6800	jessica.dooling@exxonmobil.com	Piceance Basin Field
Morgan, John		john.morgan@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
232426	WELL	TA	01/17/2020	DSPW	103-66512	U S A-PICEANCE CREEK T35-12G	TA

**General Comment:**

Routine UIC Inspection. Well temporarily abandoned.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective ActionL			Date:
Type	Main		
comment:			
Corrective ActionL			Date:

Overall Good:

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Sign at location entrance		
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	970-675-4117 or 911		
Corrective Action:			Date: _____

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment:	No
Comment:	
<input type="checkbox"/> Multiple Spills and Releases?	

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Panel fence		
Corrective Action:			Date:

<b>Equipment:</b>			corrective date
Type: Bradenhead	# 1		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:			Date:

<b>Flaring:</b>			
Type			

Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 232426 Type: WELL API Number: 103-66512 Status: TA Insp. Status: TA

**Underground Injection Control**

UIC Violation: \_\_\_\_\_ Maximum Injection Pressure: \_\_\_\_\_

UIC Routine

Inj./Tube:	Pressure or inches of Hg <u>0</u> (e.g. 30 psig or -30" Hg)	Previous Test Pressure _____	MPP _____
			Inj Zone: <u>WSTCA</u>
TC:	Pressure or inches of Hg <u>0</u>	Previous Test Pressure _____	Last MIT: <u>04/09/2020</u>
Brhd:	Pressure or inches of Hg <u>0</u>	Previous Test Pressure _____	AnnMTReq: _____

Comment: Routine UIC Inspection. Well temporarily abandoned.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Method of Injection: \_\_\_\_\_

Test Type: \_\_\_\_\_ Tbg psi: \_\_\_\_\_ Csg psi: \_\_\_\_\_ BH psi: \_\_\_\_\_

Insp. Status: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693803040	Inspection photos 4/27/2021	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5429602">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5429602</a>