

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/06/2021

Submitted Date:

05/13/2021

Document Number:

699700246

FIELD INSPECTION FORMLoc ID _____ Inspector Name: _____ On-Site Inspection ☐
Heil, John _____ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10091

Name of Operator: BERRY PETROLEUM COMPANY LLC

Address: 11117 RIVER RUN BLVD

City: BAKERSFIELD State: CA Zip: 93311

Status Summary:

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☒
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

3 Number of Comments

1 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Armstrong, Jon		jarmstrong@bry.com	
Fischer, Alex		alex.fischer@state.co.us	
Hughes, Jim		jimo.hughes@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
335568	LOCATION	AC			-	LONG RIDGE J15 595	EI
474500	SPILL OR RELEASE	CL	10/08/2020		-	Long Ridge J15	EI

General Comment:

On May 6, 2021 COGCC Environmental Staff (John Heil) conducted an environmental field inspection of BERRY PETROLEUM COMPANY LLC (Berry operator #10091) Long Ridge J15 Spill/Release Point ID 474500, Remediation #15535.

LocationOverall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	Sign not posted on the steel AST that is associated with the remediation project.		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	06/13/2021

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	335568	Type:	LOCATION	API Number:	-	Status:	AC	Insp. Status:	EI
Facility ID:	474500	Type:	SPILL OR	API Number:	-	Status:	CL	Insp. Status:	EI

Environmental**Spill/Remediation:**

Comment: COGCC staff observed a total of two structure and one steel AST associated with the remediation project. Both the western and eastern structure have an attached pipeline (2-inch steel pipeline attached to processing pipe) that leads to well API 05-045-11288 on the LONG RIDGE J15 595 Location ID 335568. Impacted material from the remediation excavation is currently being landfarmed on the LONG RIDGE J15 595 Location ID 335568.

Corrective
Action:

Date: _____

Emission Control Burner (ECB): _____

Comment:

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699700249	20210506 Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5429791