

**Inspection Photos**  
**Camenisch 1 sx Flowline Release**  
**Spill ID 479713 (AC)**



**Photo 1 – Spill area. Fencing up around open excavation.**



**Photo 2 – Spill excavation. Impacts remain in situ.**



**Inspection Photos**  
**Camenisch 1 sx Flowline Release**  
**Spill ID 479713 (AC)**



**Photo 3 – Spill excavation.**



**Photo 4 – Additional disturbed area on site. Trash observed in disturbed area.**



**Inspection Photos**  
**Camenisch 1 sx Flowline Release**  
**Spill ID 479713 (AC)**



**Photo 5 – Soils stockpiled on location. Lining does not adequately protect surface soils. Trash remains on location.**



**Photo 6 – Soils stockpiled on location. Lining does not adequately protect surface soils. BMPs inadequate for stormwater runoff.**



**Inspection Photos**  
**Camenisch 1 sx Flowline Release**  
**Spill ID 479713 (AC)**



**Photo 7 – Stained soil observed around open excavation.**



**Photo 8 – Stained soil observed around open excavation.**